


FIG. 2






FIG. 49




FIG. 4b 202




FIG. 5




FIG. 6.




FIG. 7

800 802 804 806 808 810 812




FIG. 8




FIG. 9




Figure 10: Effect of number of reorder buffer entries on clock rate for the three sequencers